

Robotic Normality Sensor

STUDENTS: Russell Kook, Jonathan Casamayor, Faisal Alsallum, Nathan Rhodes

Problem Statement

A robot normality sensor system is needed for an industrial robot that drills rivet holes for airplane manufacturing.

System Requirements

- Measure the two angles between a robot end effector and the work surface.
- Display pitch & yaw in less than a second. • 0.5° angular resolution or better.
- Sensor itself must be small (< 3" x 3" x 6").
- Various airplane surfaces (aluminum, graphite, steel, composites, alloys).

Design Approach



Fig. 1: System Block Diagram.

- We have power supplied to our two analog induction sensors.
- The sensors will take displacement readings and produce analog voltage signals which are then digitized using a data acquisition device (NI USB-6001).
- These digitized signals are then interpreted and processed through LabVIEW.
- The final results from LabVIEW is the pitch and yaw angles of a work surface relative to the sensors.

Physical System Design

- Spherical Bearing: Serves as base of sensor structure. This component is pressed up against surface and the pressure of contact will cause the inner ring of the bearing to rotate.
- Attached to the outer ring of the bearing is a support to hold a steel plate. The steel plate is necessary because the sensors only respond with ferrous metals.
- Attached to the inner ring of the bearing is a support for the sensors. The two holes in this component are where the sensors will be placed.
- The sensors will take displacement readings down to the steel plate and determine the pitch and yaw angles of rotation they make during contact with a work surface.



Fig. 2: Exploded Assembly of Sensor System.

ELECTRICAL & COMPUTER ENGINEERING

SPONSOR: Boeing

UNIVERSITY of WASHINGTON

Component Selection

- The inductance sensor was chosen because it is a non-contact sensor and had the best resolution to price ratio.
- The spherical bearing was chosen because it allows for independent rotation of two surfaces which was needed to simulate airplane manufacturing conditions.

Inner Ring

LabVIEW Interface

- Angle Calculator allows user to manually double check sensor angle outputs with trigonometry.
- Sensor Angle Calculator outputs the pitch and yaw as seen from the inductance sensors with trigonometry. Calibration buttons to calibrate the pitch and yaw sensors independently.
- Green light to indicate when a change of greater than half a degree has happened in either the pitch or yaw.

Fig. 4: Sensor Placement and Angle Calculation.

Testing

- Our test setup included two first inductance sensors 90 degrees away from each other, measuring the pitch and yaw Power Supply of a steel plate.
- With a rotating pitch axis we were able to test the system's ability to convert the analog output voltages of the sensors to degrees.
- Testing shows our system has resolution to less than half a degree and can output real time pitch and yaw readings.

ADVISORS: Ricardo Fritzke, Samuel Pedigo, Prof. Howard Chizeck, Prof. Payman Arabshahi

Fig. 3: a) Spherical bearing[1], b) Induction sensor[2].

Setup Instructions		
Distance between metal plate a	nd sensor bottom 10mm	
Angle Calculator		
Enter distance between bottom	of screw head and table top botton	n in mm
Normal is at 40mm		
Pitch Dist Yaw I	Dist	
- 37	38	
Pitch Angle Yaw A	Angle	
196086	0752	
Sensor Angle Calculator		
Sensor Angle Calculator	A1(Yaw) Voltage Input	
Sensor Angle Calculator A0(Pitch) Voltage Input	A1(Yaw) Voltage Input	
Sensor Angle Calculator A0(Pitch) Voltage Input	A1(Yaw) Voltage Input	
Sensor Angle Calculator A0(Pitch) Voltage Input	A1(Yaw) Voltage Input	
Sensor Angle Calculator A0(Pitch) Voltage Input 291413 Calibrate Pitch	A1(Yaw) Voltage Input	TO CALIBRATE ANGLES
Sensor Angle Calculator A0(Pitch) Voltage Input 291413 Calibrate Pitch	A1(Yaw) Voltage Input 4.55546 Calibrate Yaw	TO CALIBRATE ANGLES tum calibrate button on and of
Sensor Angle Cakulator A0(Pitch) Voltage Input 2.91413 Calibrate Pitch	A1(Yaw) Voltage Input 4.55546 Calibrate Yaw	TO CALIBRATE ANGLES tum calibrate button on and of
Sensor Angle Calculator A0(Pitch) Voltage Input 291413 Calibrate Pitch	A1(Yaw) Voltage Input 4.55546 Calibrate Yaw Vaw	TO CALIBRATE ANGLES tum calibrate button on and of
Sensor Angle Cakulator A0(Pitch) Voltage Input 2.91413 Calibrate Pitch Ditch 2.00522	A1(Yaw) Voltage Input 4.55546 Calibrate Yaw Vaw -1.30298	TO CALIBRATE ANGLES tum calibrate button on and of
Sensor Angle Cakulator A0(Pitch) Voltage Input 291413 Calibrate Pitch Pitch 2.00522 Pitch channe are & Degree	A1(Yaw) Voltage Input 4.55546 Calibrate Yaw Vaw Yaw -1.30298 Yaw change >= 5 Degree	TO CALIBRATE ANGLES tum calibrate button on and of
Sensor Angle Calculator A0(Pitch) Voltage Input 2.91413 Calibrate Pitch Pitch 2.00522 Pitch change >= .5 Degree	A1(Yaw) Voltage Input 4.55546 Calibrate Yaw Vaw -1.30298 Yaw change >= .5 Degree	TO CALIBRATE ANGLES tum calibrate button on and of
Sensor Angle Cakulator A0(Pitch) Voltage Input 291413 Calibrate Pitch Pitch 2.00522 Pitch change >= .5 Degree	A1(Yaw) Voltage Input 4.55546 Calibrate Yaw Vaw -1.30298 Yaw change >= .5 Degree	TO CALIBRATE ANGLES tum calibrate button on and of
Sensor Angle Cakulator A0(Pitch) Voltage Input 291413 Calibrate Pitch Pitch 2.00522 Pitch change >= .5 Degree	A1(Yaw) Voltage Input 4.55546 Calibrate Yaw Calibrate Yaw Yaw -1.30298 Yaw change >= .5 Degree	TO CALIBRATE ANGLES tum calibrate button on and of
Sensor Angle Cakulator A0(Pitch) Voltage Input 2.91413 Calibrate Pitch Pitch 2.00522 Pitch change >= .5 Degree A0(Pitch) Calibarted Voltage	A1(Yaw) Voltage Input 4.55546 Calibrate Yaw Calibrate Yaw Yaw -1.30298 Yaw change >= .5 Degree A1(Yaw) Calibarted Voltage	TO CALIBRATE ANGLES tum calibrate button on and of

Fig. 5: LabVIEW Interface.

Fig. 6: Initial Test Setup.

- rotation.
- The developed system outputs the pitch and yaw in real time.
- The system operates independent of work surface type.
- Expense for project is 60% under budget.
- Support of sensors and bearing was 3D printed at the UW BARC lab.
- Simple trigonometry was used to find the pitch and yaw angles.
- Final prototype angular resolution: 0.1°
- Using only two sensors, calibration is needed to identify at what point the plate is normal to both sensors.
- By using four sensors, this calibration could be disregarded.

Fig.7: Final Prototype.

Future Work, References, and Acknowledgments

- Improve the design structure so can be mounted to an ABB rob
- Replace 3D printed parts with machined metal parts.
- Integrate LabVIEW output to AB robot.
- Program ABB robot to reorient end effector in response to sense data.
- Add features like chip blow-off, vacuum for dust collection, and cutter lubrication.

Results

• Our final testing system allows independent pitch and yaw axis rotation from adjustable screws below the steel plate. The adjustable screws allow for fine axis

Fig.8: Budget Report Graph.

o it	[1] RBC Bearings. http://rbcbearings.com/lite
01.	rature/pdfs/SPB0520 l0.pdf
	[2] Baumer. https://www.baumer.com/medi
	as/secure/Baumer_IR30.D18L-
3B	F60.UA1E.7BO_EN_20191202_DS.pdf?mediaPK
	=8989166567454.
the	
ISOr	Faculty: Howard Chizeck, Payman Arabshahi
	Industry: Ricardo Fritzke, Samuel Pedigo
	GraduateStudent: YanaSosnovskaya